WUIR CHUEL III 3304	W	ork	Ord	er ID	5582
---------------------	---	-----	-----	-------	------

D4050-3

Strut

2/02/10

February 2, 2010 2:17:18 PM



Page 1

Item ID: **Revision ID:** Item Name: **Start Date:** Required Date: 2/02/10 Reference: Approvals:

Setup Start

Stop

**Cust Item ID: Customer:** 

Process Plan:

Date: **Tooling:**  Date:

Start Run

QC:

Date:

SPC (Y/N):

Date:

Draw

Rev.

Stop

Sequence ID/ Work Center ID **Operation Description**  Set Up/ **Run Hours**  Draw Number Plan Code

Qty

Accept Reject **Qty** 

Reject Number

Insp. Stamp

**Draw Nbr** 

**Revision Nbr** 

D4050 PA1

NC BRAKE

Memo

0.00

0.00

Brake NC Brake NC

Punch per Dwg. D4050 and Spec Control Dwg D2638

Si idozlor

110

100

Small Fab

Small Fab

Small Fab

Memo Deburr 0.00

0.00

Sa colorlor

120

QC5- Inspect part completeness to step on W/O

0.00

QC

Memo

0.00

**Quality Control** 

A Proton person

## Work Order ID 55821

February 2, 2010 2:17:18 PM



Page 2

Item ID:

D4050-3

Accept

Setup Start

Stop



**Revision ID:** 

Item Name: **Start Date:** 

Required Date: 2/02/10

Strut

Start Qty: 1.00 2/02/10

Req'd Qty: 1.00

**Cust Item ID:** 

**Customer:** 

Reference:

QC:

Operation

Description

Date: Date: Tooling:

0.00

0.00

Set Up/

**Run Hours** 

Date:

Draw

Number

Start Run

Stop

Number Stamp

**Approvals:** 

**Process Plan:** 

White Gloss(Ref:4.3.5.2) per QSI005 4.3-Steel

SPC (Y/N):

Date:

Draw

Rev.

Plan

Code

Reject

Qty

Accept

Qty

Reject Insp.

Sequence ID/ **Work Center ID** 

130

Powdercoat

Powder Coating

Memo

START TIME: OVEN TEMPERATURE:

FINISH TIME:

140

QC3- Inspect Part Finish

Memo

0.00

0.00

Quality Control

150

Packaging

Packaging

Identify as per dwg & Stock Location:

0.00

0.00

Memo

## Work Order ID 55821

February 2, 2010 2:17:19 PM



Page 3

Item ID:

D4050-3

Accept



Setup Start



**Revision ID:** 

Item Name: **Start Date:** 

Strut

QC:

2/02/10

Start Qty: 1.00 Req'd Qty: 1.00

**Cust Item ID:** 

**Customer:** 

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run Start

Required Date: 2/02/10

Date: \_\_\_\_

SPC (Y/N):

Date:

Stop

Stop

Sequence ID/ **Work Center ID** 

Operation Description

QC21- Final Inspection - Work Order Release

Set Up/ **Run Hours**  Draw Number Draw Rev.

Plan Accept Code Qty

Reject Qty

Reject Number Stamp

Insp.

160

Quality Control

Memo

0.00

0.00

POSITIVE RECALL RELEASED

U 10.02.08

February 2, 2010 2:17:15 PM

Work Order ID: 55821

Parent Item:

D4050-3

Parent Item Name:

Comments:

Strut



IPP RevA: new issue DD 10/01/05 verified by:EC

**Start Date: 2/02/10** 

Required Date: 2/02/10

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/ Item Name

Replacement Mfg/ Item ID

Purch

Bin Primary Item Location Last Location

Route Seq ID Unit of Measure Hand

Qty on

Remaining Qty Qty To Pick Issued Date Issued

Status

M304TR0.750W.049

Purchased

No

100


f

252.7810 1.3061

304 RD Tube .750 x 2049W

Warehouse	Loc Qty	Loc Code	
<b>Location</b>			
Main Warehouse			
MAT	252.781		
107518	2.77		
108498	0		
109314	8.5		
110113	0.73		
110271	0.03		
111096	9		
111457	11.43		
112652	34.39		
112800	185.931		

304 ,750 x .065 MIIOII3 1,557 At 10/02/02



THIS DOCUMENT IS PRIVATE AND COMPONITION AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERSUSSION FROM DART AEROSPACE LTD.